


Installation Monitoring Report

Project	NW 2050 Cypress Point	Job Number	24064 RGC Number		lumber	53216	
Address	7511, 7531, 7651 Minoru Boulevard	Inspector	Matthew	Report Number		23	
	Richmond, B.C.	Weather	Sun / 26°C	Time		12:00pm	
Contractor	Flynn Canada Ltd.	Crew Size	22 Red Sea	l 6	Apprentices 13		13

Date: July 8, 2025

Distribution List: keith.lodge@flynncompanies.com, ken.brown@flynncompanies.com, nw2050@telus.net. matt@phoenixroofconsultants.ca



23.1 **Building B**


Base wall flashing has begun to be installed on the East deck location.



23.2 **Building B**

With the pavers reinstated this has left gaps along the perimeter. It is recommended they be filled with additional same style rubber pavers rather than oversized base flashing.

The roofing contractor is looking into cost to present to the Strata Council.



23.3 **Building C**

Installation of the parapet flashing is nearly completed and the double gum lip installation at the stucco wall has begun.



23.4 **Building C**

Perforated vent strip flashing has begun to be applied along the tops of the parapet but under the capping detail.



23.5 **Building C**

Incorrect stripping details at BUR vent have been corrected.



23.6 **Building A**

Prep work is well underway to the Northwest deck area.



23.7 Building A

Tiles and fencing have been moved aside and the old roof deck sprayed clean.



23.8 Building A

Overview of the main roof from the scaffolding.



23.9 Building A

From the water test carried out by the foreman the day prior, identified ponding water locations have received additional build up to promote positive drainage and mitigate further ponding in that location.



23.10 Building A

Ducting will require extensions where crickets have been applied



23.11 Building A

Additional screws and plates are being applied to the field of the boards and patched in an acceptable manner with Sopraply stick DUO.



23.12 **Building A**

Application of Sopraply Stick Traffic Cap has begun on the South side of the main roof.

Cap rolls have been laid out to be relaxed prior to installation.



23.13 Building A

The cap membrane is being rolled into an Elastocol Stick primed surface, adhesion to date appears acceptable.



23.14 **Building A**

Robotic air welders are being used to complete heat welding of the side laps.

Welds to date appear acceptable.



Outstanding Items:

N/A

Reported by:

Matthew Blackstock, RRO Phoenix Roof Consultants

Phoenix Roof Consultants field reviews are for general conformance to specifications and roofing compliance only. Our reviews are not to take the place of the contractor's own quality control which shall remain the responsibility of the contractor. Phoenix Roof Consultants will not be responsible for acts or omissions of the contractor or for the contractor's failure to fulfill the intent of the specifications, contract, or quote.