


Installation Monitoring Report

Project	NW 2050 Cypress Point	Job Number	24064	RGC Number		53216	
Address	7511, 7531, 7651 Minoru Boulevard	Inspector	Matthew	Report Number		33	
	Richmond, B.C.	Weather	Sun / 26°C Time		11:20am		
Contractor	Flynn Canada Ltd.	Crew Size	7 Red Seal	3	Apprentices		4

Date: August 11, 2025

Distribution List: keith.lodge@flynncompanies.com, ken.brown@flynncompanies.com, nw2050@telus.net. matt@phoenixroofconsultants.ca




33.1 Building B

Installation of the perimeter cap flashing is completed.



33.2 **Building B**

Interior securement with the interior color matching cladding screws to be snugged up with the spacer in a few locations.



33.3 **Building B**

An interior white flashing clover in process being applied to cover the exposed wood.



33.4 Building B

Additional wood trim to be installed behind the opening mechanism, roofing contractor to ensure it is painted before securement.



33.5 **Building B**

Roofing contractor to fully remove covering without scratching the surface, if it cannot be done then it will require to be fully replaced with new.



33.6 **Building B**

Roofing Contractor to confirm these are the Dayliter VCM Insulite skylights.



33.7 **Building B**

Some of the skylights were noted to have a warped plastic frame, Roofing contractor to review with skylight manufacturer and replace deformed frames.



Outstanding Items:

• Item #31.2 = Strata council to review.

Reported by:

Matthew Blackstock, RRO Phoenix Roof Consultants

Phoenix Roof Consultants field reviews are for general conformance to specifications and roofing compliance only. Our reviews are not to take the place of the contractor's own quality control which shall remain the responsibility of the contractor. Phoenix Roof Consultants will not be responsible for acts or omissions of the contractor or for the contractor's failure to fulfill the intent of the specifications, contract, or quote.