


Installation Monitoring Report

Project	NW 2050 Cypress Point	Job Number	24064	RGC Number		53216	
Address	7511, 7531, 7651 Minoru Boulevard	Inspector	Matthew	Report Number		39	
	Richmond, B.C.	Weather	Cloud / 26°C Time			1:50pm	
Contractor	Flynn Canada Ltd.	Crew Size	5 Red Seal	3	Apprent	ices	2

Date: August 28, 2025

Distribution List: keith.lodge@flynncompanies.com, ken.brown@flynncompanies.com, nw2050@telus.net. matt@phoenixroofconsultants.ca



39.1 Building A

Flashing installation continues on the lower deck areas.



39.2 **Building A**

Installation of the 24ga cross broken panels is well underway to the parapets.



39.3 **Building A**

S-lock flashing corner details are being applied.



39.4 Building A

Perforated insect screen was applied over the wall vent details as required.



39.5 **Building A**

S-locks are being created in an acceptable manner at corners.



39.6 **Building A**

Inside corners of the cap flashing were found acceptable.



39.7 Building A

The membrane termination edge is not uniformed. An Alsan flashing, with taped edges and granules to be applied along the membrane application.



39.8 Building A

Skylights details, fencing, and final drain details remain to be applied.



Outstanding Items:

• Items #34.6 - 34.8

Reported by:

Matthew Blackstock, RRO Phoenix Roof Consultants

Phoenix Roof Consultants field reviews are for general conformance to specifications and roofing compliance only. Our reviews are not to take the place of the contractor's own quality control which shall remain the responsibility of the contractor. Phoenix Roof Consultants will not be responsible for acts or omissions of the contractor or for the contractor's failure to fulfill the intent of the specifications, contract, or quote.