


Installation Monitoring Report

| Project | NW 2050 Cypress Point | Job Number | 24064 | RGC Number | | 53216 | |
|------------|--------------------------------------|---------------|------------|---------------|---------|--------|---|
| Address | 7511, 7531, 7651 Minoru Boulevard | Inspector | Matthew | Report Number | | 45 | |
| | Richmond, B.C. | Weather | Sun / 24°C | Time | | 2:30pm | |
| Contractor | Flynn Canada Ltd. | Crew Size | 0 Red Seal | 0 | Apprent | ices | 0 |

Date: September 17, 2025

Distribution List: keith.lodge@flynncompanies.com, ken.brown@flynncompanies.com, nw2050@telus.net, matt@phoenixroofconsultants.ca



45.1 **Building A**

The balance of the cap flashing has finished being applied where the scaffolding was set up.



45.2 **Building A**

The interface of the cap flashing was secured high on the cap flashing due to spacing concerns from the top plate to the wall.

Additional long cladding screws with spacer tubes as stated in the specifications to be installed at the bottom edge of the cap flashing at S-locks and halfway between seams.



45.3 Building A

Rust inhibiting paint has finished being applied to the roof hatch area.



45.4 **Building A**

The mechanical units in closure flashing have also been applied.




45.5 **Building A**

Previously noted membrane repair has been corrected in an acceptable manner.



45.6 **Building A**

The balance of paver work, skylights, privacy screens, oversized debris screens and outstanding items listed below to be completed.



Outstanding Items:

• Items #34.6 – 34.8, #39.7, #40.5 - 40.13.

Reported by:

Matthew Blackstock, RRO Phoenix Roof Consultants

Phoenix Roof Consultants field reviews are for general conformance to specifications and roofing compliance only. Our reviews are not to take the place of the contractor's own quality control which shall remain the responsibility of the contractor. Phoenix Roof Consultants will not be responsible for acts or omissions of the contractor or for the contractor's failure to fulfill the intent of the specifications, contract, or quote.